

FIG. 1 (RELATED ART)




FIG. 2 (RELATED ART)

Metal	Resistivity(μΩ·cm)	Price	Adhesive Strength	Heat Resistance
Cu	2	Low	Bad	Good
Au	3	High	Bad	Good
Al	4	Low	Good	Bad
Mo	10	Middle	Good	Good
Cr	25	Middle	Good	Good

FIG. 3 (RELATED ART)




FIG. 4




FIG. 5




FIG. 6A




FIG. 6B




FIG. 6C